




WIRING







DIMENSIONS



FRONT VIEW CALIBRATION POTENTIOMETER HOLE LOCATION




CUTOUT & BEZEL ASSEMBLY




IS-054

Rev. 2J17


WIRING







DIMENSIONS



FRONT VIEW CALIBRATION POTENTIOMETER HOLE LOCATION



CUTOUT & BEZEL ASSEMBLY



IS-054

Rev. 2J17